# GOVERNMENT OF TELANGANA ABSTRACT

Minor Irrigation – Krishna Basin – Siddipet District - "Mission Kakatiya Phase-III" - "Comprehensive Restoration of (26) Minor Irrigation tanks in Siddipet District – Administrative approval - Accorded – Orders - Issued.

\_\_\_\_\_\_

## **IRRIGATION & CAD (MK) DEPARTMENT**

G.O.Rt.No. 428 Dated: 18-04-2017.

Read the following:-

1. From the Chief Engineer, Minor Irrigation (KB), Hyderabad, Lr.No. DCE-I/OT1 - AEE5 / Mission Kakatiya-III/Siddipet / List–XI/ 2017, Dt: 27-02-2017.

- 2. From the Chief Engineer, Minor Irrigation, Hyderabad, Lr.No.20193/ DCE-II/ OT1/TO2/Budget/checkslips/2017, Dt.19-01-2017.
- 3. From the Chief Engineer, Minor Irrigation, Hyderabad, Lr.No.CE/ MI/DCE1/ OT1/AEE5/Finance Department/Remarks/2017, dated:09-03-2017.

\*\*\*

# ORDER:-

Government of Telangana has taken-up restoration of all Minor Irrigation Tanks in the State to their original capacity and to effectively utilize water allocated for Minor Irrigation sector under Godavari & Krishna River Basins as a flagship programme under the name of "MISSION KAKATIYA".

- 2. The Chief Engineer, Minor Irrigation (KB), Hyderabad in his letter first read above has submitted proposal under Mission Kakatiya Phase-III for "Comprehensive Restoration of (27) Minor Irrigation tanks in Siddipet District for according administrative approval.
- 3. Government after careful examination of the matter, hereby accord administrative approval for an amount of Rs.9,07,42,000/-(Rupees Nine Crores Seven lakhs and Forty Two Thousand Only) towards "Comprehensive Restoration of (26) Minor Irrigation tanks in Siddipet District for the Financial Year 2017-18 under Mission Kakatiya phase-III Programme, subject to the responsibility of the Chief Engineer, Minor Irrigation (KB), Hyderabad, to follow the following points while giving Technical Sanction and while executing the work. The statement showing the details of tank sanctioned for restoration is annexed to this order:-
  - He must ensure and satisfy from the history of repairs carried out to the tanks that there are no overlap of proposed repairs in any other previous sanctioned schemes, now on-going are taken up recently.
  - 2) The cost of repairs must be arrived after thorough investigation and as per the actual requirement of components are quantities for restoration and the provisions made including lump sum provisions are in terms of codal provisions and the guidelines issued in relation thereto.
  - 3) Whenever applicable, the de-siltation provision made in the estimates are based pre-levels and prudent assessment of quantities involved and in consideration of nature of percolation and potential of the yield.

- 4) Follow due procurement procedures for taking up the works.
- 5) Dismantling of existing damage Structures and construction of new weir and sluice shall be done only in rare cases after due examination of the possibilities of repairs of the existing damage structures at a level not lower than Superintending Engineer.
- 6) Ensure sufficient funds in 2017-18 BE to meet the expenditure towards MK programme works including sanctions considered now before giving technical sanction.
- 7) Recheck the arithmetical accuracy of individual provisions and total estimate cost.
- 8) The Superintending Engineer must inspect and check the cost benefit ratio for all the tanks which is having ayacut less than 10 acres or the cost per acre is more than Rs.50,000/-
- 4. The expenditure sanctioned in para (3) above shall be debited to the Head of Account "4702 COL on M.I. MH-101-Surface Water GH-11 Normal State Plan SH-(23) Mission Kakatiya 530 Major works 531 Other Expenditure".
- 5. The Chief Engineer, Minor Irrigation (KB), Hyderabad, shall take necessary action accordingly to complete the work within the stipulated period and submit the utilization certificate to Government. The (26) estimates received through the letter 1<sup>st</sup> read above are returned herewith.
- 6. This order issues with the concurrence of Finance (EBS.IX) Department vide their U.O. No.3740/263/A2/EBS.IX/2017, Dated:10.04.2017.

#### (BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

## VIKAS RAJ PRINCIPAL SECRETARY TO GOVERNMENT

T۸

The Chief Engineer, Minor Irrigation (KB), Hyderabad (we) (26) original Estimates Copy to:-

The District Collector, Siddipet.

The Accountant General, T.S. Hyderabad.

The Director of Works & Accounts, M.J. Market Road, T.S., Hyderabad.

The PS to Hon'ble Minister (Irrgn, Mrkt, and LA)

The PS to Principal Secretary to Government, I & CAD Department.

The PA to Deputy Secretary to Government, I & CAD Department.

The Finance (EBS.IX) Department.

SF/SCs (C.No.C.No.2057/MK/A2/2017)

//forwarded by order //

**SECTION OFFICER** 

Continued	annexure					
Continuca	armonarc	 		•		

ANNEXURE – I Statement showing the details of tanks sanctioned for Restoration under Mission Kakatiya Phase –III Siddipet District - List - XI

SI.no	Unique Code	Geo-tagging ID	Name of the Tank	Habitation H/O Village	Mandal	Constituency	Ayacut	Amount Sanctioned for Repairs of Component Rs.ln Lakh	Amount Sanctioned for Desiltaion Rs.In Lakh	Total Sanctioned for the work Rs. in Lakhs
1	2	3	4	5	6	7	8	9	10	11
1	040421900303401	788424180077	Nagireddy Kunta	Marpadaga H/o Nagireddypally	Kondapak	Gajwel	40.0	10.99	0.99	11.98
2	040421901001407	788410179995	Gangasani Kunta	Sirisinagandla	Kondapak	Gajwel	75.0	39.17	0.58	39.75
3	030304602101101	790568181944	Guggilla anicut/ Jalu Kalva	Guggila	Bejjanki	Manakondur (SC)	303.0	66.00	0.00	66.00
4	040414601301312	787124180074	Mangaloni Kunta/ Mangalivani Kunta	Thoguta	Thoguta	Dubbak	35.0	10.89	1.98	12.87
5	090980100601313	790013179152	Devunibai Kunta	Cheriyal	Cheriyal	Jangon	35.0	11.54	3.31	14.85
6	030325502101303	792012180674	Kotha Kunta	Janagaon	Akkannapet	Husnabad	30.0	16.11	1.89	18.00
7	040331700201310	788641182281	Peddamma Kunta /Mallanna Gutta Kunta	Vittalapur	Chinnakodur	Siddipet	90.0	123.70	0.00	123.70
8	090980100601310	790295179508	Gandhi Kunta	Rampur H/o Akunoor	Cheriyal	Jangon	30.0	5.70	5.60	11.30
9	090980201401301	790329179185	Venkat Reddy cheruvu	Maddur	Siddipet	Siddipet	32.0	8.20	7.70	15.90
10	090980201401801	790466179130	Oota cheruvu	Maddur	Maddur	Jangon	40.0	20.94	6.31	27.25
11	090980101601101	790032178756	Yelkashetty Kunta/ Elka chettu Kunta	Veerannapet	Cheriyal	Jangon	60.0	24.22	11.98	36.20
12	090980200701303	790937179935	Gadda Kunta/ Bundla Kunta/ Jogi Kunta	Bekkal	Maddur	Jangon	35.0	11.35	2.25	13.60
13	040414601301309	787035180071	Kummari Kunta/Kummari Kunta	Thoguta	Thoguta	Dubbak	35.0	12.62	0.00	12.62
14	040411400101302	786013182231	Kotha Kunta	Gambheerpur	Dubbak	Dubbak	40.0	27.02	2.28	29.30

15	040411400901802	786957182013	Kandugula Chervu/ Nalla cheru (Kandula cheru)	Chellapur	Dubbak	Dubbak	72.3	47.71	2.49	50.20
16	040411400501103	786765181633	Nalla cheru	Dubbak	Dubbak	Dubbak	128.4	44.15	3.85	48.00
17	040414601001102	787354180629	Pedda cheruvu	Gudikandula	Thoguta	Dubbak	152.2	35.52	4.08	39.60
18	040411400501303	786484181919	Lingapagari Kunta (Bodappagari Kunta)	Dubbak	Dubbak	Dubbak	40.0	17.40	0.00	17.40
19	040414601101101	787849180143	Pedda cheruvu	Peddamasan pally	Thoguta	Dubbak	186.3	63.31	2.69	66.00
20	040414603501101	787221180326	Pedda cheruvu	Kangal	Thoguta	Dubbak	286.3	64.45	2.00	66.45
21	040424401401301	785839178018	Kotha Kunta	Madaram H/o Amberpet	Wargal	Gajwel	14.0	9.88	1.37	11.25
22	040424502701303	785050176927	Lachamma Kunta	Bandamailaram	Mulugu	Gajwel	22.0	9.17	2.93	12.10
23	040422001901306	787702177954	Kapparavani Kunta	Allirajpet	Jagadevpur	Gajwel	20.0	8.82	0.13	8.95
24	040422002301309	788117177729	Gundaiah Kunta	Jagadevpur	Jagadevpur	Gajwel	20.0	6.01	0.89	6.90
25	040414600801302	786919179865	Pedda cheruvu	Chandapur	Thoguta	Dubbak	85.0	57.55	2.70	60.25
26	040412302001101	784683179760	Oora cheruvu	Chegunta	Chegunta	Dubbak	110.0	78.90	8.10	87.00
27	040331702201305	789348181369	Construction of DLRB across Siddipet vagu near Gonepally (V), Gonepally to Chinnakodur (V) Road	Chinnakodur	Chinnakodur	Siddipet		0.00	0.00	
27							2016.51	831.30	76.12	907.42

VIKAS RAJ PRINCIPAL SECRETARY TO GOVERNMENT

//forwarded by order //

**SECTION OFFICER**